## **Under Review Notification**

Raised By: Vanessa Morel Product #: RB6893739

Date: 2019.11.07 Product Name: OIL SLINGER AND SEAL REAR COMPRESSOR BEA

		"Y" or "N" Required for Each Part Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)		IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RB6893739	RB6893739 Rev	Υ	Υ	N	Υ	Υ	N	N	N	19-1253	See below

## Description of Issue:

Issues stated on ADR (Napkin drawing)

RB6893739 must be put on **HOLD** in Plex

RB6893739 Finish good stock must be put in quarantine

All subs and parts in stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations Chief Engineer Production Engineers Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene